broas 博瑞思

正本

CMA 152512050049

检 测 报 告

TEST REPORT

报告编号 Report No：YNZKBG2024090923

项目名称 Name：华新水泥（昭通）有限公司2024年第三季度自行监测

委托单位 Client：华新水泥（昭通）有限公司

项目地址 Address：昭通市昭阳区北闸镇塘房村

声　　明

Introduction

This report no seal on the perforation and CMA qualification certification seal and special seal for testing is invalid.

company are based on the information provided by the entrusting party. When the information

assume any responsibilities arising therefrom.

Address:

Postcode ID:

Telephone No:

Fax No:

Website:

监测期间运行情况	运行负荷
正常	99.6%

NO.1

检测项目	检测依据	仪器名称	仪器编号	检出限/检测质浓度
高锰酸盐指数	GB/T 11892-1989	滴定管	YN-SK-XC497	0.5mg/L
溶解总磷	GB/T 11893-1989	可见分光光度计	YN-SK-FX007	0.01mg/L
总磷	GB/T 11893-1989	可见分光光度计	YN-SK-FX149	0.01mg/L
氨氮	HJ 535-2009	可见分光光度计	YN-SK-FX086	0.025mg/L
总氮	HJ 636-2012	紫外可见分光光度计	YN-SK-FX281	0.05mg/L
硝酸盐氮	HJ/T 346-2007	可见分光光度计	YN-SK-FX088	0.08mg/L

NO.2

质	
	L
	L

broas 博瑞思

地下水检测结果表

1#

V002

YN

24072

4×

0

0

末

0

7

7.6

标

标

标

| | | |

地下水监测点


水是生命之源
请节约用水
纬度：27°26.550
地址：云南省昭通市昭阳区
352国道华新水泥昭通有限公
司（西北门）
时间：2024-08-02
16:10:00
海拔：2072.4米
备注：地下水